

X-Validate 3.1 Release Notes

09th September 2011



These release notes are divided into four sections:

1. Installing X-Tools
2. New features in this release
3. Known issues in this release
4. Bugs fixed in this release

1. Installing X-Tools

Important

Uninstall the previous version of X-Tools before installing a new version.
Close any open ACRA CONTROL tools before installing/uninstalling other ACRA CONTROL tools.

Note 1: X-Tools installation is not supported on the Windows 2000 operating system, as the installation includes .NET framework 4.0.

Note 2: The user should install and run X-Validate as an administrator on a Windows 7 operating system. This also applies to installation of Microsoft .NET Framework version 4.0.

2. New features in this release

For new features, see X-Validate data sheet

3. Known issues in this release

Issue #	Description
XVD-72	Unhelpful error message "ERROR_PARSER_LOADFAILED" generated when XidML version is 2.41
XVD-102	The 'Display Next Time' setting no longer appears on the GUI
XVD-113	The message server window blocks X-Validate window
XVD-115	Opening a second instance of X-Validate will result in it crashing
XVD-133	The behavior of progress bar is dependent on the size of test file under validation
XVD-135	X-Validate failed to validate of task file with PBM/001

4. Bugs fixed in this release

N/A